

REPLACEMENT SHEET

INTERNAL COMBUSTION ENGINE/HYDRAULIC MOTOR/FLUID PUMP PROVIDED WITH OPPOSITE PISTONS
Michael Arseneau - Serial No. 10/615,373
Confirmation No. 1385 - Docket No. A-8632.RCE




FIG. - 12A






FIG. - 12B

REPLACEMENT SHEET

INTERNAL COMBUSTION ENGINE/HYDRAULIC MOTOR/FLUID PUMP PROVIDED WITH OPPOSITE PISTONS

Michael Arseneau - Serial No. 10/615,373

Confirmation No. 1385 - Docket No. A-8632.RCE



REPLACEMENT SHEET

INTERNAL COMBUSTION ENGINE/HYDRAULIC MOTOR/FLUID PUMP PROVIDED WITH OPPOSITE PISTONS

Michael Arseneau - Serial No. 10/615,373

Confirmation No. 1385 - Docket No. A-8632.RCE




Figure 15a




Figure 15b




Figure 14a




Figure 14b




Figure 16




Figure 17